



# United States Department of the Interior

## BUREAU OF LAND MANAGEMENT

Color Country District Office  
Henry Mountains Field Station

PO Box 99  
Hanksville, Utah 84734  
Telephone (435)542-3461

S/017/0043  
CC: Wayne



### In Reply Refer To:

3809  
(UTC021)  
UTU-71615  
S/017/0043

December 8, 2011

Certified Mail – Return Receipt Requested  
Certified Mail No. 7009 3410 0001 1113 6456

Mr. Avraham Azoulay  
Martinique Mining Corporation  
2335 Northwest 107<sup>th</sup> Avenue, Suite 2M46  
Doral, Florida 33172

Subject: Follow-up to letter dated November 29, 2011

Dear Mr. Azoulay:

This letter is to follow-up with you on site inspections of the May Day Mill/Crescent Creek Operations and corrective actions that were requested by letter dated November 29, 2011. A follow-up inspection of the May Day Mill (UTU-71615) site was conducted on December 7, 2011. The following items detailed in the November 29, 2011 letter had not been addressed:

- **Stained soil removal requirements:**  
Martinique Mining Corporation is directed to immediately excavate and place all affected soil into DOT approved sealable 55 gallon drums for transport to a properly licensed disposal facility. Further, Martinique Mining Corporation is directed to provide proof of transport and disposal of affected soil at a properly licensed disposal facility in the form of a facility receipt, chain-of-custody documents, and/or laboratory analysis results.
- **Unauthorized release sampling requirements:**  
Martinique Mining Corporation is directed to retain a qualified third party to conduct confirmation sampling in the area affected by unauthorized release to assure complete removal of deleterious liquids. Bureau of Land Management (BLM) will review and approve third party qualifications and the recommended

RECEIVED

DEC 09 2011


DIV. OF OIL, GAS & MINING

sampling and laboratory analysis program prior to the sampling event. BLM personnel will be on-site and observe any soil sampling event.

When the May Day Mill site was visited on December 7, 2011, there was less than an inch of snow on the ground and removal of the affected soil would still be feasible. Due to concerns regarding weather conditions at the site, BLM hereby requests that substantial progress be made towards completing the work detailed above for the soil removal and sampling within ten (10) days of receipt of this letter.

If you have questions regarding this matter, please contact me at (435)542-3461. Please coordinate directly with John Reay, Geologist regarding the third party sampling and necessary compliance visits to the site.

Sincerely,



Sue Fivecoat  
Assistant Field Office Manager

cc: Wayne Western, UDOGM